

## Annexure D

### **BUILDING SAFETY CERTIFICATE**

25 SEP 2025

No.PB/Building-1/  
CoE 32 /2025

Dated: 25 Sep. 2025

It is certified that the existing **My School, Near Choundeshwri Cotton Mill, Sangali Kolhapur Highway at Chipri Tal.Shirol Dist.Kolhapur** is having block (s) / Floor (s) as per details below:

| Detail of Block(s) In School  | Block (1)   | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|-------------------------------|-------------|-----------|-----------|-----------|-----------|-----------|
| No. of Floor (s) in the Block | Basment G+3 | -         | -         | -         | -         | -         |

The building is owned/occupied by **My School, Near Choundeshwri Cotton Mill, Sangali Kolhapur Highway at Chipri Tal.Shirol Dist.Kolhapur** have compiled with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Works Division, Tarabai Park, Kolhapur** on **29/08/2025** in the presence of **Shri.B.B. Vadade (Administrative Officer)** that the building/premises is fit for occupancy for running school with effect from **29 / 08 / 2025** for a period of **1 (one)** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Any addition and / or alteration or any damage to the structural frame caused by accident or by tampering with the geometrical sections or structural member for any purpose whatsoever.
2. Overloading of the structure or lack of maintenance or any act that is detrimental to the structure as a whole

Issued on 16/09/2025 by Office of Executive Engineer at Public Work Division, Tarabai Park, Kolhapur-416003



(Rohit V. Tondale)  
Executive Engineer,  
P.W.Division, Kolhapur.

\*Strike out whichever is not applicable, In case of block is more than six use separate sheet for detail.